



Read The Full Story

# RAPID HELIPAD CONCRETE REPAIR



## Epoxy Aggregate Repair Ready for Helicopter Traffic in 48 Hours

A hospital trauma center faced a critical challenge with its helipad suffering from freeze/thaw damage and dislodged concrete chunks, posing a threat to helicopter safety and staff. Traditional repair methods would take a month, causing significant interruptions to helipad service. Banks Industrial Group provided a rapid solution, completing the helipad repair in under 48 hours using Belzona materials. Belzona 4131 epoxy mortar was applied for rapid and robust repair, followed by Belzona 5111 protective coating, ensuring extended lifespan and enhanced safety. The efficient repair minimized downtime, addressing the hospital's crucial mission of providing emergency and trauma services.



Areas of concrete damage cut out and patched with Belzona 4131.

- 1 Helicopter traffic was stirring up concrete chunks
- 2 Concrete spall deterioration
- 3 Areas of damage are cut out and patched
- 4 Final protective coating application



856-687-2227 • [sales@banksindustrial.com](mailto:sales@banksindustrial.com) • [BanksIndustrial.com](http://BanksIndustrial.com)  
 PO Box 382 • Berlin, NJ 08009